

Report date: 27th July 2015

Table: Average water quality for Kampala during the period of 20th - 26th July 2015

Parameter						Monitoring points									
	National Standard For portable water	Ntinda	Lubowa	Kabowa	Seguku	Kibuye	Kololo	Muyenga	Naguru	Mulago	Mengo	Nalumunye	Mukono	Kitintale	Rubaga
pH	6.6-8.5	7.2	7.2	7.1	7.1	7.0	7.2	7.2	7.0	7.2	6.9	7.0	7.0	7.0	7.1
Electrical Conductivity (µs/cm)	≤1500	131	131	136	130	136	131	133	131	134	130	134	130	130	130
Turbidity (NTU)	≤5.00	0.78	0.63	0.69	0.82	0.65	0.75	0.78	0.71	0.68	0.57	0.72	0.77	0.63	0.53
Colour (PtCo)	≤15	8	4	9	8	5	9	8	6	8	5	7	9	4	8
Escherichia coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Faecal coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/L)	0.2-0.5	0.35	0.30	0.25	0.30	0.35	0.35	0.40	0.35	0.30	0.25	0.30	0.25	0.35	0.30