

Report date: 17th August 2015

Table: Average water quality for Kampala during the period of 10th - 14th August 2015

Parameter	Standard for portable water	Monitoring Points													
		City Centre	Nakawa	Bweyogerere	Katwe	Busega	Buloba	Mutundwe	Buziga	Makindye	Mengo	Mbuya	Naguru	Ntinda	Kiwatule
pH	6.5-8.5	7.3	7.0	7.0	7.2	7.0	7.0	7.0	7.1	7.1	7.1	7.1	7.2	7.2	7.4
Electrical Conductivity ($\mu\text{S/cm}$)	1500	126	136	136	127	136	139	135	136	137	136	136	133	131	133
Turbidity (NTU)	5	0.46	0.55	0.57	0.59	0.65	0.88	0.74	0.53	0.52	0.76	0.79	0.68	0.51	0.66
Colour (PtCo)	15	4	5	7	9	9	11	10	8	6	10	11	9	7	10
Esherichia coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Feacal coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/l)	0.20 – 0.50	0.30	0.25	0.25	0.20	0.25	0.20	0.25	0.30	0.30	0.20	0.25	0.30	0.25	0.25