

Report date: 21st December 2015

Table: Average water quality for Kampala during the period of 14th - 18th December 2015

Parameter	Standard for portable water	Monitoring Points													
		Nakasero	Old Kampala	Nakulabye	Namugoona	Nansana	Kalerwe	Bweyogerere	Mutungo	Nsambya	Munyonyo	Namuwongo	Kasubi	City Centre	Wakiso
	6.5-8.5	7.5	7.2	7.5	7.7	7.8	7.6	7.4	7.8	7.5	7.1	7.3	7.6	7.6	6.8
Electrical Conductivity ($\mu\text{s/cm}$)	1500	155	161	158	161	158	157	140	156	157	153	156	157	160	168
Turbidity (NTU)	5	0.42	0.99	0.77	0.94	0.89	0.75	0.64	0.62	0.88	0.71	0.67	0.86	0.70	0.77
Colour (PtCo)	15	8	10	9	13	12	9	7	9	11	6	10	9	8	4
Esherichia coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Feacal coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/l)	0.20 – 0.50	0.30	0.20	0.30	0.20	0.20	0.40	0.20	0.30	0.25	0.40	0.20	0.30	0.30	0.25

