

Report date: 7th December 2015

Table: Average water quality for Kampala during the period of 30th Nov - 4th December 2015

Parameter	Standard for portable water	Monitoring Points													
		Kalerwe	Kisenyi	Buziga	Kiwatule	Gaba	Bunamwaya	Seeta	Kamwokya	Kisaasi	Mutundwe	Mengo	Busabala	Luzira	Nakulabye
pH	6.5-8.5	7.3	7.3	7.3	8.0	7.8	7.9	7.9	7.6	7.8	7.9	8.0	7.5	7.6	8.0
Electrical Conductivity (μ S/cm)	1500	161	144	155	143	158	187	174	171	144	180	175	157	164	173
Turbidity (NTU)	5	0.68	0.53	0.41	0.99	0.42	0.97	0.75	0.58	0.92	0.84	0.87	0.46	0.81	0.66
Colour (PtCo)	15	8	7	2	14	3	10	9	7	13	11	9	3	10	7
Esherichia coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Feacal coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/l)	0.20 – 0.50	0.40	0.25	0.45	0.20	0.45	0.30	0.30	0.30	0.20	0.20	0.25	0.45	0.40	0.20

