

Report date: 14th December 2015

Table: Average water quality for Kampala during the period of 7th - 11th December 2015

Parameter	Standard for portable water	Monitoring Points													
		City Centre	Katwe	Ndejje	Naalya	Busega	Bwaise	Mukono	Naguru	Komamboga	Mbuya	Kyanja	Buloba	Lubowa	Wakiso
pH	6.5-8.5	7.1	7.2	7.2	7.0	7.1	7.5	7.3	7.0	7.5	7.0	7.0	7.3	7.3	6.3
Electrical Conductivity ($\mu\text{S}/\text{cm}$)	1500	149	150	152	150	158	154	157	147	152	151	152	172	154	148
Turbidity (NTU)	5	0.66	0.95	0.97	0.00	0.81	0.72	0.93	0.48	1.00	0.74	0.00	0.68	0.61	0.67
Colour (PtCo)	15	5	9	11	0	12	7	10	4	14	8	0	10	11	2
Esherichia coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Feacal coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/l)	0.20 – 0.50	0.25	0.20	0.40	0.40	0.20	0.30	0.20	0.35	0.20	0.30	0.35	0.20	0.35	0.20

