

Report date: 23rd November 2015

Table: Average water quality for Kampala during the period of 16th - 20th November 2015

Parameter	Standard for portable water	Monitoring Points													
		Rubaga	Bwaise	Namasuba	City Centre	Bunamwaya	Naguru	Kulambiro	Bweyogerere	Old Kampala	Luzira	Lubowa	Namugongo	Komamboga	Seeta
pH	6.5-8.5	7.9	7.7	7.5	7.7	7.8	7.8	7.7	7.6	7.7	7.6	7.6	7.3	7.5	7.7
Electrical Conductivity ($\mu\text{s/cm}$)	1500	156	168	148	149	155	154	147	154	151	153	147	141	162	152
Turbidity (NTU)	5	0.64	0.57	0.55	0.79	0.88	0.78	0.82	0.71	0.74	0.94	0.66	0.37	0.96	0.94
Colour (PtCo)	15	9	4	5	8	12	10	11	9	9	10	7	8	7	10
Esherichia coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Feacal coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/l)	0.20 – 0.50	0.30	0.25	0.35	0.30	0.20	0.30	0.20	0.25	0.20	0.30	0.25	0.30	0.25	0.25

