

Report date: 16th November 2015

Table: Average water quality for Kampala during the period of 9th - 14th November 2015

Parameter	Standard for portable water	Monitoring Points													
		Mengo	Bwaise	Makindye	Kisenyi	Gayaza	Mulago	Mutungo	Busega	Kyambogo	Kisaasi	Munyonyo	Kyebando	Mbuya	Nateete
pH	6.5-8.5	7.7	7.7	7.6	7.6	7.0	7.1	7.2	7.8	7.6	7.6	7.7	7.1	7.3	7.7
Electrical Conductivity ($\mu\text{S}/\text{cm}$)	1500	138	141	146	149	178	146	152	142	150	148	140	146	153	142
Turbidity (NTU)	5	0.79	0.91	0.83	0.97	0.76	0.81	0.62	0.82	0.56	0.98	0.44	0.99	0.87	0.80
Colour (PtCo)	15	7	10	9	11	8	7	8	10	8	12	5	8	9	11
Esherichia coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Feacal coliform (cfu/100 mL)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/l)	0.20 – 0.50	0.30	0.20	0.40	0.25	0.20	0.30	0.30	0.20	0.35	0.20	0.45	0.30	0.25	0.25