

Report date: 17<sup>th</sup> July 2023

Table: Average water quality for Kampala Water during the period running 10<sup>th</sup> - 16<sup>th</sup> July 2023

Parameter	National Standard For Potable Water	Monitoring Points															
		Namamve Booster	Kirinya Bukasa	MUBS Nakawa	Nakulabye market	Mengo Bulange	Wampewo Avenue	Ntinda Ministers' Village	Najjera II	Sonde Trading Center	Mutungo Zone III	Kiswa Health Centre	Makerere Kubiri	Bunga market	Salaama Road	Mukono Kayunga Road	Seeta Market
Sample ID		10470	10472	10479	10548	10550	10563	10507	10511	10524	10525	10534	10574	10631	10628	10615	10617
Electrical Conductivity (µs/cm)	≤1500	103	103	135	138	142	135	121	119	102	107	141	142	142	138	102	102
pH	6.5-8.5	7.5	7.4	7.0	7.3	7.1	7.2	7.2	7.2	7.4	7.7	7.1	7.2	6.8	6.9	7.7	7.7
Turbidity (NTU)	≤5	0.46	0.30	0.28	0.56	0.80	0.47	0.72	0.51	0.49	0.55	0.48	0.40	0.95	0.91	0.44	0.20
Colour – Apparent (PtCo)	≤15	4	4	0	9	9	6	8	5	5	5	5	5	8	3	4	0
Escherichia Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Fecal Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/L)	0.20-0.50	0.45	0.30	0.30	0.40	0.40	0.40	0.23	0.26	0.25	0.20	0.30	0.30	0	0.30	0.28	0.30

**Remarks**

The physio-chemical and bacteriological quality of the supplied water in the Network distribution complied with the National Standards for potable water.



Denis Smith Akejo  
**Senior Quality Control Officer – KW**

Written by:



Enos Malambala  
**Quality Assurance Manager – KW**

Approved by: