

Report date: 24th July 2023

Table: Average water quality for Kampala Water during the period running 17th - 23rd July 2023

Parameter	National Standard For Potable Water	Monitoring Points															
		Mbuya Comboni Sisters	Luzira Kirombe	Kireka Market	Lake Victoria Serena - Mutungo	Ndejje Kanyanya Zone	Matuga Kyogogwa Village	Mawanda Road - Denaro Apartment	Makerere Primary School	Kawempe Mbogo Islamic	Kalinabiri Ntinda	Kyaliwajjala Trading Center	Kyambogo UPK	Kisenyi Bus Terminal	Cooper Complex	Buddo Trading Center	Bunamwaya Ngobe
Sample ID		12608	12614	12618	12633	12637	12681	12686	12688	12690	12668	12671	12672	12696	12703	12713	12715
Electrical Conductivity (µs/cm)	≤1500	151	151	151	138	141	150	147	149	149	125	107	148	149	156	155	146
pH	6.5-8.5	7.1	7.2	7.1	7.4	7.4	7.1	7.2	7.1	7.2	7.4	7.9	7.3	7.2	7.2	7.4	7.4
Turbidity (NTU)	≤5	0.44	0.86	0.39	0.71	0.68	0.58	0.70	0.70	0.68	0.57	0.45	0.37	0.59	0.70	0.69	0.48
Colour – Apparent (PtCo)	≤15	4	5	4	11	7	6	8	8	9	5	5	3	5	7	8	5
Escherichia Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Fecal Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/L)	0.20-0.50	0.45	0.30	0.40	0.30	0.40	0.25	0.40	0.24	0.30	0.35	0.40	0.30	0.30	0.30	0.30	0.30

Remarks

The physio-chemical and bacteriological quality of the supplied water in the Network distribution complied with the National Standards for potable water.



Denis Smith Akejo
Senior Quality Control Officer – KW

Written by:



Enos Malambala
Quality Assurance Manager – KW

Approved by: