

Report date: 11th December 2023

Table: Average water quality for Kampala Water during the period running 04th - 10th December 2023

Parameter	National Standard For Potable Water	Monitoring Points														
		Ggaba Road PV	Kansanga Rainbow	Nsambya St. Peter's School	Namboole Stadium Hotel	Bweyogerere Kazinga Zone	Banda Market	Naguru Police Barracks	Busabala Road, Masajja TC	Busabala - Kirinda C	Arkrigh Road Seeta - Near Hill Top P/S	Sonde Trading Center	Jomayi Estates Nabusugwe	Namusera Trading Center	Bandwe Booster	Bugolobi Resurrection Church Of Uganda
Electrical Conductivity (µs/cm)	≤1500	126	128	129	95	93	128	127	131	127	103	110	91	132	127	103
pH	6.5-8.5	7.7	7.8	7.6	8.0	7.9	7.8	7.7	8.1	7.6	8.2	8.2	8.1	7.6	7.6	8.2
Turbidity (NTU)	≤5	0.71	0.96	0.97	0.48	0.45	0.80	0.88	0.27	0.94	0.38	0.90	0.87	1.29	0.75	0.61
Colour – Apparent (PtCo)	≤15	3	4	6	0	0	0	9	0	8	0	6	0	14	4	2
Escherichia Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Fecal Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total Coliforms (CFU/100m/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Residual Chlorine (mg/L)	0.20-0.50	0.30	0.30	0.30	0.30	0.35	0.40	0.35	0.30	0.40	0.30	0.40	0.25	0.40	0.40	0.30
Suspended Solids (mg/L)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Remarks

The physio-chemical and bacteriological quality of the supplied water in the Network distribution complied with the National Standards for potable water.



Denis Smith Akejo
Senior Quality Control Officer – KW

Written by:



Enos Malambala
Quality Assurance Manager – KW

Approved by: